

Tulsa Gas Technologies, Inc.  
 4309 S. 101st. E. Ave.  
 Tulsa, OK 74146  
 918-665-2641

Work Order # GHEM100423TS  
 Customer Name GHEM Construction S  
 Customer PO NA  
 Date Required 5-3-24

ASSEMBLY/CERTIFICATION SHEET

	SIGN	DATE						
1 <input checked="" type="checkbox"/> Review shop work order versus customer print and history	PM	5-3-24						
2 <input checked="" type="checkbox"/> Component part numbers: <u>105CG-0-6, 101CG-4-6</u> Pack dates and/or QC codes	PM	5-3-24						
3 <input checked="" type="checkbox"/> ID band number <u>5CNG6/52ON4-0501/0106-64/24-120"</u>	PM	5-3-24						
4 <input checked="" type="checkbox"/> Hose Cut Length <u>120"</u>	PM	5-3-24						
5 <input type="checkbox"/> Pre-expansion of hose (if required) Size _____ Remarks: _____								
6 <input checked="" type="checkbox"/> Audit and mark appropriate insertion depth	PM	5-3-24						
7 <input type="checkbox"/> Add special accessories _____ Remarks: _____								
8 <input checked="" type="checkbox"/> Apply danger tag and ID band	PM	5-3-24						
9 <input checked="" type="checkbox"/> Install bend restrictors Remarks: _____	PM	5-3-24						
10 <input checked="" type="checkbox"/> Assemble fittings; check insertion depth Remarks: _____	PM	5-3-24						
11 <input type="checkbox"/> Set offset angle and/or orientation Remarks: _____								
12 <input checked="" type="checkbox"/> Perform crimp or swage on product/crimp set die-using Parker Catalog 4660, page K58 <table border="0" style="margin-left: 40px;"> <tr> <td>_____ 1/2) 80C-PO8H</td> <td>_____ 3/8) 80C-PO6H</td> </tr> <tr> <td>_____ 1/4) 80C-PO4H</td> <td>_____ 1/8) 80C-PO2</td> </tr> <tr> <td><input checked="" type="checkbox"/> 3/8) 80C-PO6</td> <td>_____ 3/4) 80C-P12H</td> </tr> </table>	_____ 1/2) 80C-PO8H	_____ 3/8) 80C-PO6H	_____ 1/4) 80C-PO4H	_____ 1/8) 80C-PO2	<input checked="" type="checkbox"/> 3/8) 80C-PO6	_____ 3/4) 80C-P12H	PM	5-3-24
_____ 1/2) 80C-PO8H	_____ 3/8) 80C-PO6H							
_____ 1/4) 80C-PO4H	_____ 1/8) 80C-PO2							
<input checked="" type="checkbox"/> 3/8) 80C-PO6	_____ 3/4) 80C-P12H							
13 <input type="checkbox"/> Add special accessories after crimping/swaging								
14 <input type="checkbox"/> Perform and record burst test results, if applicable Remarks: _____								
15 <input type="checkbox"/> Air test, if applicable Test pressure Psi _____ Seconds _____; Pass/Fail (Circle One) Remarks: _____								
16 <input checked="" type="checkbox"/> Hydrostatic proof test Test pressure Psi <u>10,000</u> Seconds <u>30</u> <input checked="" type="checkbox"/> Pass/Fail (Circle One) Remarks: _____	PM	5-3-24						
17 <input checked="" type="checkbox"/> Flush method water, and then air	PM	5-3-24						
18 <input checked="" type="checkbox"/> Perform and record conductivity test; Meter _____ Megger Mit200 Hose resistance <u>0.09</u> (-) Electrode resistance _____ 0.03 (=) Final hose resistance <u>0.03</u>	PM	5-3-24						
19 <input checked="" type="checkbox"/> Final audit: Check boxes for items inspected, as applicable: <input checked="" type="checkbox"/> Correct hose; <input checked="" type="checkbox"/> Correct fittings; <input checked="" type="checkbox"/> Correct customer PN Check swage or crimp diameters: _____ 5CNG-4-58 .668/.688 <input checked="" type="checkbox"/> 5CNG-4-58 .785/.805 _____ 5CNG-8-58 .900/.920 <input checked="" type="checkbox"/> 5CNG-6-55 .675/.695 _____ 5CNG-12-58 1.20/1.22 *****100% VISUAL INSPECT FOR THE FOLLOWING***** <input checked="" type="checkbox"/> Hose fittings crimped; <input checked="" type="checkbox"/> Air passes through assembly; <input checked="" type="checkbox"/> Presence of threads	PM	5-3-24						
20 <input checked="" type="checkbox"/> Cap and package hose	PM	5-3-24						
	PM	5-3-24						

Tulsa Gas Technologies, Inc.  
 4809 S. 101st. E. Ave.  
 Tulsa, OK 74146  
 918-665-2641

Work Order # GHEM100423TS  
 Customer Name GHEMM Construction  
 Customer PO NA  
 Date Required 5-3-24

ASSEMBLY/CERTIFICATION SHEET

	SIGN	DATE
1 <input checked="" type="checkbox"/> Review shop work order versus customer print and history	PM	5-3-24
2 <input checked="" type="checkbox"/> Component part numbers: <u>105CG1-6-6 ; 101CG1-4-4</u> Pack dates and/or QC codes _____	PM	5-3-24
3 <input checked="" type="checkbox"/> ID band number <u>5CNG16/520N4-0501/0106-64/24-120"</u>	PM	5-3-24
4 <input checked="" type="checkbox"/> Hose Cut Length <u>120"</u>	PM	5-3-24
5 _____ Pre-expansion of hose (if required) Size _____ Remarks: _____		
6 <input checked="" type="checkbox"/> Audit and mark appropriate insertion depth	PM	5-3-24
7 _____ Add special accessories _____ Remarks: _____		
8 <input checked="" type="checkbox"/> Apply danger tag and ID band	PM	5-3-24
9 <input checked="" type="checkbox"/> Install bend restrictors Remarks: _____	PM	5-3-24
10 <input checked="" type="checkbox"/> Assemble fittings; check insertion depth Remarks: _____	PM	5-3-24
11 _____ Set offset angle and/or orientation Remarks: _____		
12 <input checked="" type="checkbox"/> Perform crimp or swage on product/crimp set die-using Parker Catalog 4660, page K53  <div style="display: flex; justify-content: space-between; margin-left: 20px;"> <div style="width: 45%;"> <p>_____ 1/2) 80C-PO8H</p> <p><input checked="" type="checkbox"/> 1/4) 80C-PO4H</p> <p><input checked="" type="checkbox"/> 3/8) 80C-PO6</p> </div> <div style="width: 45%;"> <p>_____ 3/8) 80C-PO6H</p> <p>_____ 1/8) 80C-PO2</p> <p>_____ 3/4) 80C-P12H</p> </div> </div>	PM	5-3-24
13 _____ Add special accessories after crimping/swaging		
14 _____ Perform and record burst test results, if applicable Remarks: _____		
15 _____ Air test, if applicable Test pressure Psi _____ Seconds _____; Pass/Fail (Circle One) Remarks: _____		
16 <input checked="" type="checkbox"/> Hydrostatic proof test Test pressure Psi <u>10,000</u> Seconds <u>30</u> <span style="border: 1px solid black; border-radius: 50%; padding: 2px;">Pass</span> /Fail (Circle One) Remarks: _____	PM	5-3-24
17 <input checked="" type="checkbox"/> Flush method water, and then air	PM	5-3-24
18 <input checked="" type="checkbox"/> Perform and record conductivity test; Meter _____ Megger Mit200 Hose resistance <u>0.04</u> (-) Electrode resistance <u>0.03</u> (=) Final hose resistance <u>0.03</u>	PM	5-3-24
19 <input checked="" type="checkbox"/> Final audit: Check boxes for items inspected, as applicable: <input checked="" type="checkbox"/> Correct hose; <input checked="" type="checkbox"/> Correct fittings; <input checked="" type="checkbox"/> Correct customer PN Check swage or crimp diameters: _____ 5CNG-4-58 .668/.688 <input checked="" type="checkbox"/> 5CNG-4-58 .785/.805    _____ 5CNG-8-58 .900/.920 <input checked="" type="checkbox"/> 5CNG-6-55 .675/.695    _____ 5CNG-12-58 1.20/1.22	PM	5-3-24
*****100% VISUAL INSPECT FOR THE FOLLOWING*****		
_____ <input checked="" type="checkbox"/> Hose fittings crimped;    _____ <input checked="" type="checkbox"/> Air passes through assembly;		
_____ <input checked="" type="checkbox"/> Presence of threads	PM	5-3-24
20 <input checked="" type="checkbox"/> Cap and package hose	PM	5-3-24
_____	PM	5-3-24

105CG-6-6

101CG-4-6

3

- FITTING TYPE
- 01 NPT MALE
  - 02 NPT FEMALE
  - 03 JIC MALE
  - 04 SAE 45 MALE
  - 05 SAE O-RING STRAIGHT THREAD
  - 06 JIC FEMALE SWIVEL

7

- FITTING SIZE
- 4 1/4"
  - 6 3/8"
  - 8 1/2"
  - 12 3/4"

1

- CG SERIES HOSE SIZE
- 4 1/4"
  - 6 3/8"
  - 8 1/2"
  - 12 3/4"

4

- FITTING TYPE
- 01 NPT MALE
  - 02 NPT FEMALE
  - 03 JIC MALE
  - 04 SAE 45 MALE
  - 05 SAE O-RING STRAIGHT THREAD
  - 06 JIC FEMALE SWIVEL


8

- FITTING SIZE
- 4 1/4"
  - 6 3/8"
  - 8 1/2"
  - 12 3/4"

BREAK-AWAY OR DISPENSER END

FILL END

Cut 122"  
11 FILL HOSE LENGTH  
170"



5

- FITTING TYPE
- 01 NPT MALE
  - 02 NPT FEMALE
  - 03 JIC MALE
  - 04 SAE 45 MALE
  - 05 SAE O-RING STRAIGHT THREAD
  - 06 JIC FEMALE SWIVEL

9

- FITTING SIZE
- 2 1/8"
  - 4 1/4"
  - 6 3/8"

2

- CG SERIES HOSE SIZE
- 4 1/4"
  - 6 3/8"

6

- FITTING TYPE
- 01 NPT MALE
  - 02 NPT FEMALE
  - 03 JIC MALE
  - 04 SAE 45 MALE
  - 05 SAE O-RING STRAIGHT THREAD
  - 06 JIC FEMALE SWIVEL

10

- FITTING SIZE
- 2 1/8"
  - 4 1/4"
  - 6 3/8"

WORK ORDER #

1 5CNG6/520N4-05a/0106-69/24-120"

TULSA HOSE WORKING CORP. INC.	
1017 EAST 10TH STREET	
TULSA, OK 74146	
DATE: 03/27/97	CHECKED BY:
DESIGNED BY: C. SEWELL	SCALE: NONE
DRAWN BY: C.R.S.	SHEET NO. OF
DWG. NO. FILLHOSE 5CNG 5CNG	REV. 3

FILL HOSE

Tulsa Gas Technologies, Inc.  
 4809 S. 101st. E. Ave.  
 Tulsa, OK 74146  
 918-665-2641

Work Order # GHEM100423TS  
 Customer Name GHEM Construction  
 Customer PO NA  
 Date Required 5-3-24

ASSEMBLY/CERTIFICATION SHEET

	SIGN	DATE						
1 <input checked="" type="checkbox"/> Review shop work order versus customer print and history	<u>PM</u>	<u>5-3-24</u>						
2 <input checked="" type="checkbox"/> Component part numbers: <u>105CG-6-6, 106CG-8-6</u> Pack dates and/or QC codes _____	<u>PM</u>	<u>5-3-24</u>						
3 <input checked="" type="checkbox"/> ID band number <u>5CNG6/520N4-0506/0100-68/24-24"</u>	<u>PM</u>	<u>5-3-24</u>						
4 <input checked="" type="checkbox"/> Hose Cut Length <u>24"</u>	<u>PM</u>	<u>5-3-24</u>						
5 _____ Pre-expansion of hose (if required) Size _____ Remarks: _____								
6 <input checked="" type="checkbox"/> Audit and mark appropriate insertion depth	<u>PM</u>	<u>5-3-24</u>						
7 _____ Add special accessories _____ Remarks: _____								
8 <input checked="" type="checkbox"/> Apply danger tag and ID band	<u>PM</u>	<u>5-3-24</u>						
9 <input checked="" type="checkbox"/> Install bend restrictors Remarks: _____	<u>PM</u>	<u>5-3-24</u>						
10 <input checked="" type="checkbox"/> Assemble fittings; check insertion depth Remarks: _____	<u>PM</u>	<u>5-3-24</u>						
11 _____ Set offset angle and/or orientation Remarks: _____								
12 <input checked="" type="checkbox"/> Perform crimp or swage on product/crimp set die-using Parker Catalog 4660, page K53  <table border="0" style="width: 100%;"> <tr> <td>_____ 1/2) 80C-PO8H</td> <td>_____ 3/8) 80C-PO6H</td> </tr> <tr> <td><input checked="" type="checkbox"/> 1/4) 80C-PO4H</td> <td>_____ 1/8) 80C-PO2</td> </tr> <tr> <td><input checked="" type="checkbox"/> 3/8) 80C-PO6</td> <td>_____ 3/4) 80C-P12H</td> </tr> </table>	_____ 1/2) 80C-PO8H	_____ 3/8) 80C-PO6H	<input checked="" type="checkbox"/> 1/4) 80C-PO4H	_____ 1/8) 80C-PO2	<input checked="" type="checkbox"/> 3/8) 80C-PO6	_____ 3/4) 80C-P12H	<u>PM</u>	<u>5-3-24</u>
_____ 1/2) 80C-PO8H	_____ 3/8) 80C-PO6H							
<input checked="" type="checkbox"/> 1/4) 80C-PO4H	_____ 1/8) 80C-PO2							
<input checked="" type="checkbox"/> 3/8) 80C-PO6	_____ 3/4) 80C-P12H							
13 _____ Add special accessories after crimping/swaging _____								
14 _____ Perform and record burst test results, if applicable Remarks: _____								
15 _____ Air test, if applicable Test pressure Psi _____ Seconds _____; Pass/Fail (Circle One) Remarks: _____								
16 <input checked="" type="checkbox"/> Hydrostatic proof test Test pressure Psi <u>10.000</u> Seconds <u>30</u> ; <u>Pass</u> /Fail (Circle One) Remarks: _____	<u>PM</u>	<u>5-3-24</u>						
17 <input checked="" type="checkbox"/> Flush method water, and then air	<u>PM</u>	<u>5-3-24</u>						
18 <input checked="" type="checkbox"/> Perform and record conductivity test; Meter _____ Megger Mit200 Hose resistance <u>0.00</u> (-) Electrode resistance <u>0.03</u> (=) Final hose resistance <u>0.03</u>	<u>PM</u>	<u>5-3-24</u>						
19 <input checked="" type="checkbox"/> Final audit: Check boxes for items inspected, as applicable: <input checked="" type="checkbox"/> Correct hose; <input checked="" type="checkbox"/> Correct fittings; <input checked="" type="checkbox"/> Correct customer PN Check swage or crimp diameters: _____ 5CNG-4-58 .668/.688 <input checked="" type="checkbox"/> 5CNG-4-58 .785/.805 _____ 5CNG-8-58 .900/.920 <input checked="" type="checkbox"/> 5CNG-6-55 .675/.695 _____ 5CNG-12-58 1.20/1.22 *****100% VISUAL INSPECT FOR THE FOLLOWING***** <input checked="" type="checkbox"/> Hose fittings crimped; <input checked="" type="checkbox"/> Air passes through assembly; <input checked="" type="checkbox"/> Presence of threads	<u>PM</u>	<u>5-3-24</u>						
20 <input checked="" type="checkbox"/> Cap and package hose	<u>PM</u>	<u>5-3-24</u>						
	<u>PM</u>	<u>5-3-24</u>						

Tulsa Gas Technologies, Inc.  
 4809 S. 101st. E. Ave.  
 Tulsa, OK 74146  
 918-665-2641

Work Order # GHEM100423TS  
 Customer Name GHEM Construction  
 Customer PO NA  
 Date Required 5-3-24

ASSEMBLY/CERTIFICATION SHEET

- |   | SIGN      | DATE          |
|---|-----------|---------------|
| 1 <input checked="" type="checkbox"/> Review shop work order versus customer print and history  | <u>PM</u> | <u>5-3-24</u> |
| 2 <input checked="" type="checkbox"/> Component part numbers: <u>105CG-6-6, 106CG-8-6</u>   |           |               |
| Pack dates and/or QC codes  | <u>PM</u> | <u>5-3-24</u> |
| 3 <input checked="" type="checkbox"/> ID band number <u>5CNG6/520N4-0506/0106-68/24-24"</u>   | <u>PM</u> | <u>5-3-24</u> |
| 4 <input checked="" type="checkbox"/> Hose Cut Length <u>24"</u>  | <u>PM</u> | <u>5-3-24</u> |
| 5 ___ Pre-expansion of hose (if required) Size _____  |           |               |
| Remarks: _____  |           |               |
| 6 <input checked="" type="checkbox"/> Audit and mark appropriate insertion depth  | <u>PM</u> | <u>5-3-24</u> |
| 7 ___ Add special accessories _____   |           |               |
| Remarks: _____  |           |               |
| 8 <input checked="" type="checkbox"/> Apply danger tag and ID band  | <u>PM</u> | <u>5-3-24</u> |
| 9 <input checked="" type="checkbox"/> Install bend restrictors  |           |               |
| Remarks: _____  | <u>PM</u> | <u>5-3-24</u> |
| 10 <input checked="" type="checkbox"/> Assemble fittings; check insertion depth   |           |               |
| Remarks: _____  | <u>PM</u> | <u>5-3-24</u> |
| 11 ___ Set offset angle and/or orientation  |           |               |
| Remarks: _____  |           |               |
| 12 <input checked="" type="checkbox"/> Perform crimp or swage on product/crimp set die-using Parker Catalog 4660, page K53                                      |           |               |
| _____ 1/2) 80C-PO8H   |           |               |
| _____ 1/4) 80C-PO4H   |           |               |
| <input checked="" type="checkbox"/> 3/8) 80C-PO6  |           |               |
| _____ 3/8) 80C-PO6H   |           |               |
| _____ 1/8) 80C-PO2  |           |               |
| _____ 3/4) 80C-P12H   | <u>PM</u> | <u>5-3-24</u> |
| 13 ___ Add special accessories after crimping/swaging   |           |               |
| 14 ___ Perform and record burst test results, if applicable   |           |               |
| Remarks: _____  |           |               |
| 15 ___ Air test, if applicable  |           |               |
| Test pressure Psi _____ Seconds _____; Pass/Fail (Circle One)   |           |               |
| Remarks: _____  |           |               |
| 16 <input checked="" type="checkbox"/> Hydrostatic proof test   |           |               |
| Test pressure Psi <u>10,000</u> Seconds <u>30</u> <u>Pass</u> /Fail (Circle One)  |           |               |
| Remarks: _____  | <u>PM</u> | <u>5-3-24</u> |
| 17 <input checked="" type="checkbox"/> Flush method water, and then air   | <u>PM</u> | <u>5-3-24</u> |
| 13 <input checked="" type="checkbox"/> Perform and record conductivity test; Meter _____ Megger Mit200  |           |               |
| Hose resistance <u>0.00</u> (-) Electrode resistance <u>0.03</u>  |           |               |
| (=) Final hose resistance <u>0.03</u>   | <u>PM</u> | <u>5-3-24</u> |
| 19 <input checked="" type="checkbox"/> Final audit: Check boxes for items inspected, as applicable:   |           |               |
| <input checked="" type="checkbox"/> Correct hose; <input checked="" type="checkbox"/> Correct fittings; <input checked="" type="checkbox"/> Correct customer PN |           |               |
| Check swage or crimp diameters: _____ 5CNG-4-58 .668/.688   |           |               |
| <input checked="" type="checkbox"/> 5CNG-4-58 .785/.805 _____ 5CNG-8-58 .900/.920   | <u>PM</u> | <u>5-3-24</u> |
| <input checked="" type="checkbox"/> 5CNG-6-55 .675/.695 _____ 5CNG-12-58 1.20/1.22  |           |               |
| *****100% VISUAL INSPECT FOR THE FOLLOWING*****   |           |               |
| <input checked="" type="checkbox"/> Hose fittings crimped; _____ Air passes through assembly;   |           |               |
| <input checked="" type="checkbox"/> Presence of threads   | <u>PM</u> | <u>5-3-24</u> |
| 20 <input checked="" type="checkbox"/> Cap and package hose   | <u>PM</u> | <u>5-3-24</u> |
| _____   | <u>PM</u> | <u>5-3-24</u> |

105CG-6-6

106CG-8-6

3

- FITTING TYPE
- 01 NPT MALE
- 02 NPT FEMALE
- 03 JIC MALE
- 04 SAE 45 MALE
- 05 SAE O-RING STRAIGHT THREAD
- 06 JIC FEMALE SWIVEL

7

- FITTING SIZE
- 4 1/4"
- 6 3/8"
- 8 1/2"
- 12 3/4"

1

- CG SERIES
- HOSE SIZE
- 4 1/4"
- 6 3/8"
- 8 1/2"
- 12 3/4"

4

- FITTING TYPE
- 01 NPT MALE
- 02 NPT FEMALE
- 03 JIC MALE
- 04 SAE 45 MALE
- 05 SAE O-RING STRAIGHT THREAD
- 06 JIC FEMALE SWIVEL

8


- FITTING SIZE
- 4 1/4"
- 6 3/8"
- 8 1/2"
- 12 3/4"

BREAK-AWAY OR DISPENSER END

Cut 26"

11 FILL HOSE LENGTH 24"

Disp - FILL-END



STANDARD 3" OPW CT1000 P36 5/8"

5

- FITTING TYPE
- 01 NPT MALE
- 02 NPT FEMALE
- 03 JIC MALE
- 04 SAE 45 MALE
- 05 SAE O-RING STRAIGHT THREAD
- 06 JIC FEMALE SWIVEL

9

- FITTING SIZE
- 2 1/8"
- 4 1/4"
- 6 3/8"

2

- CG SERIES
- HOSE SIZE
- 4 1/4"
- 6 3/8"

6

- FITTING TYPE
- 01 NPT MALE
- 02 NPT FEMALE
- 03 JIC MALE
- 04 SAE 45 MALE
- 05 SAE O-RING STRAIGHT THREAD
- 06 JIC FEMALE SWIVEL

10

- FITTING SIZE
- 2 1/8"
- 4 1/4"
- 6 3/8"

WORK ORDER #GHEM100423TS

5CNG 1/520NH 2 3 4 5 6 7 8 9 10 11 05 06 1 01 06 - 68 / 24 - 24"

TULSA GAS TECHNOLOGIES, INC.	
101 W. SAS. HWY. 51	
TULSA, OK 74116	
DATE: 03/27/97	CHECKED BY:
DESIGNED BY: C. SEWELL	SCALE: NONE
DRAWN BY: C.P.S.	SHEET NO. OF
DWG. NO.: FILLHOSE 5CNG 5CNG	REV. 3

Tulsa Gas Technologies, Inc.  
 4809 S. 101st. E. Ave.  
 Tulsa, OK 74146  
 918-665-2641

Work Order # GHEM100423TS  
 Customer Name GHEM Construction  
 Customer PO NA  
 Date Required 5-3-24

ASSEMBLY/CERTIFICATION SHEET

	SIGN	DATE									
1 <input checked="" type="checkbox"/> Review shop work order versus customer print and history	PM	5-3-24									
2 <input checked="" type="checkbox"/> Component part numbers: <u>106CG-12-12, 106CG-12-12</u> Pack dates and/or QC codes	PM	5-3-24									
3 <input checked="" type="checkbox"/> ID band number <u>5CNG12/5CNG12-0606/0506-1212/66-96"</u>	PM	5-3-24									
4 <input checked="" type="checkbox"/> Hose Cut Length <u>96"</u>	PM	5-3-24									
5 <input type="checkbox"/> Pre-expansion of hose (if required) Size _____ Remarks: _____											
6 <input checked="" type="checkbox"/> Audit and mark appropriate insertion depth	PM	5-3-24									
7 <input type="checkbox"/> Add special accessories _____ Remarks: _____											
8 <input checked="" type="checkbox"/> Apply danger tag and ID band	PM	5-3-24									
9 <input checked="" type="checkbox"/> Install bend restrictors Remarks: _____	PM	5-3-24									
10 <input checked="" type="checkbox"/> Assemble fittings; check insertion depth Remarks: _____	PM	5-3-24									
11 <input type="checkbox"/> Set offset angle and/or orientation Remarks: _____											
12 <input checked="" type="checkbox"/> Perform crimp or swage on product/crimp set die-using Parker Catalog 4660, page K58  <table border="0" style="width: 100%;"> <tr> <td>_____ 1/2) 80C-PO8H</td> <td>_____ 3/8) 80C-PO6H</td> <td></td> </tr> <tr> <td>_____ 1/4) 80C-PO4H</td> <td>_____ 1/8) 80C-PO2</td> <td></td> </tr> <tr> <td>_____ 3/8) 80C-PO6</td> <td><input checked="" type="checkbox"/> 3/4) 80C-P12H</td> <td>PM 5-3-24</td> </tr> </table>	_____ 1/2) 80C-PO8H	_____ 3/8) 80C-PO6H		_____ 1/4) 80C-PO4H	_____ 1/8) 80C-PO2		_____ 3/8) 80C-PO6	<input checked="" type="checkbox"/> 3/4) 80C-P12H	PM 5-3-24		
_____ 1/2) 80C-PO8H	_____ 3/8) 80C-PO6H										
_____ 1/4) 80C-PO4H	_____ 1/8) 80C-PO2										
_____ 3/8) 80C-PO6	<input checked="" type="checkbox"/> 3/4) 80C-P12H	PM 5-3-24									
13 <input type="checkbox"/> Add special accessories after crimping/swaging _____											
14 <input type="checkbox"/> Perform and record burst test results, if applicable Remarks: _____											
15 <input type="checkbox"/> Air test, if applicable Test pressure Psi _____ Seconds _____; Pass/Fail (Circle One) Remarks: _____											
16 <input checked="" type="checkbox"/> Hydrostatic proof test Test pressure Psi <u>10,000</u> Seconds <u>30</u> <input checked="" type="checkbox"/> Pass/Fail (Circle One) Remarks: _____	PM	5-3-24									
17 <input checked="" type="checkbox"/> Flush method water, and then air	PM	5-3-24									
18 <input checked="" type="checkbox"/> Perform and record conductivity test; Meter _____ Megger Mit200 Hose resistance <u>0.01</u> (-) Electrode resistance <u>0.03</u> (=) Final hose resistance <u>0.03</u>	PM	5-3-24									
19 <input checked="" type="checkbox"/> Final audit: Check boxes for items inspected, as applicable: <input checked="" type="checkbox"/> Correct hose; <input checked="" type="checkbox"/> Correct fittings; <input checked="" type="checkbox"/> Correct customer PN Check swage or crimp diameters: _____ 5CNG-4-58 .668/.688 _____ 5CNG-4-58 .785/.805 _____ 5CNG-8-58 .900/.920 _____ 5CNG-6-55 .675/.695 <input checked="" type="checkbox"/> 5CNG-12-58 1.20/1.22 *****100% VISUAL INSPECT FOR THE FOLLOWING***** <input checked="" type="checkbox"/> Hose fittings crimped; <input checked="" type="checkbox"/> Air passes through assembly; <input checked="" type="checkbox"/> Presence of threads	PM	5-3-24									
20 <input checked="" type="checkbox"/> Cap and package hose	PM	5-3-24									
	PM	5-3-24									

Tulsa Gas Technologies, Inc.  
4809 S. 101st. E. Ave.  
Tulsa, OK 74146  
918-665-2641

Work Order # GHEM100423TS  
Customer Name GHEM construction  
Customer PO N/A  
Date Required 5-3-24

ASSEMBLY/CERTIFICATION SHEET

	SIGN	DATE												
1 <input checked="" type="checkbox"/> Review shop work order versus customer print and history	<u>PM</u>	<u>5-3-24</u>												
2 <input checked="" type="checkbox"/> Component part numbers: <u>106CG-12-12, 106CG-12-12</u> Pack dates and/or QC codes	<u>PM</u>	<u>5-3-24</u>												
3 <input checked="" type="checkbox"/> ID band number <u>5CNG12/5CNG16-0606/0506-1212/64-96"</u>	<u>PM</u>	<u>5-3-24</u>												
4 <input checked="" type="checkbox"/> Hose Cut Length <u>96"</u>	<u>PM</u>	<u>5-3-24</u>												
5 <input type="checkbox"/> Pre-expansion of hose (if required) Size _____ Remarks: _____														
6 <input checked="" type="checkbox"/> Audit and mark appropriate insertion depth	<u>PM</u>	<u>5-3-24</u>												
7 <input type="checkbox"/> Add special accessories _____ Remarks: _____														
8 <input checked="" type="checkbox"/> Apply danger tag and ID band	<u>PM</u>	<u>5-3-24</u>												
9 <input checked="" type="checkbox"/> Install bend restrictors Remarks: _____	<u>PM</u>	<u>5-3-24</u>												
10 <input checked="" type="checkbox"/> Assemble fittings; check insertion depth Remarks: _____	<u>PM</u>	<u>5-3-24</u>												
11 <input type="checkbox"/> Set offset angle and/or orientation Remarks: _____														
12 <input checked="" type="checkbox"/> Perform crimp or swage on product/crimp set die-using Parker Catalog 4660, page K58 <table border="0" style="margin-left: 40px;"><tr><td>_____ 1/2) 80C-PO8H</td><td>_____ 3/8) 80C-PO6H</td></tr><tr><td>_____ 1/4) 80C-PO4H</td><td><input checked="" type="checkbox"/> 1/8) 80C-PO2</td></tr><tr><td><input checked="" type="checkbox"/> 3/8) 80C-PO6</td><td><input checked="" type="checkbox"/> 3/4) 80C-P12H</td></tr></table>	_____ 1/2) 80C-PO8H	_____ 3/8) 80C-PO6H	_____ 1/4) 80C-PO4H	<input checked="" type="checkbox"/> 1/8) 80C-PO2	<input checked="" type="checkbox"/> 3/8) 80C-PO6	<input checked="" type="checkbox"/> 3/4) 80C-P12H	<u>PM</u>	<u>5-3-24</u>						
_____ 1/2) 80C-PO8H	_____ 3/8) 80C-PO6H													
_____ 1/4) 80C-PO4H	<input checked="" type="checkbox"/> 1/8) 80C-PO2													
<input checked="" type="checkbox"/> 3/8) 80C-PO6	<input checked="" type="checkbox"/> 3/4) 80C-P12H													
13 <input type="checkbox"/> Add special accessories after crimping/swaging														
14 <input type="checkbox"/> Perform and record burst test results, if applicable Remarks: _____														
15 <input type="checkbox"/> Air test, if applicable Test pressure Psi _____ Seconds _____; Pass/Fail (Circle One) Remarks: _____														
16 <input checked="" type="checkbox"/> Hydrostatic proof test Test pressure Psi <u>10,000</u> Seconds <u>30</u> ; Pass/Fail (Circle One) Remarks: _____	<u>PM</u>	<u>5-3-24</u>												
17 <input checked="" type="checkbox"/> Flush method water, and then air	<u>PM</u>	<u>5-3-24</u>												
18 <input checked="" type="checkbox"/> Perform and record conductivity test; Meter _____ Megger Mit200 Hose resistance <u>0.01</u> (-) Electrode resistance <u>0.03</u> (=) Final hose resistance <u>0.03</u>	<u>PM</u>	<u>5-3-24</u>												
19 <input checked="" type="checkbox"/> Final audit: Check boxes for items inspected, as applicable: <table border="0" style="margin-left: 40px;"><tr><td><input checked="" type="checkbox"/> Correct hose;</td><td><input checked="" type="checkbox"/> Correct fittings;</td><td><input checked="" type="checkbox"/> Correct customer PN</td></tr><tr><td>Check swage or crimp diameters: _____ 5CNG-4-58 .668/.688</td><td></td><td></td></tr><tr><td>_____ 5CNG-4-58 .785/.805</td><td><input checked="" type="checkbox"/> 5CNG-8-58 .900/.920</td><td></td></tr><tr><td>_____ 5CNG-6-55 .675/.695</td><td><input checked="" type="checkbox"/> 5CNG-12-58 1.20/1.22</td><td></td></tr></table>	<input checked="" type="checkbox"/> Correct hose;	<input checked="" type="checkbox"/> Correct fittings;	<input checked="" type="checkbox"/> Correct customer PN	Check swage or crimp diameters: _____ 5CNG-4-58 .668/.688			_____ 5CNG-4-58 .785/.805	<input checked="" type="checkbox"/> 5CNG-8-58 .900/.920		_____ 5CNG-6-55 .675/.695	<input checked="" type="checkbox"/> 5CNG-12-58 1.20/1.22		<u>PM</u>	<u>5-3-24</u>
<input checked="" type="checkbox"/> Correct hose;	<input checked="" type="checkbox"/> Correct fittings;	<input checked="" type="checkbox"/> Correct customer PN												
Check swage or crimp diameters: _____ 5CNG-4-58 .668/.688														
_____ 5CNG-4-58 .785/.805	<input checked="" type="checkbox"/> 5CNG-8-58 .900/.920													
_____ 5CNG-6-55 .675/.695	<input checked="" type="checkbox"/> 5CNG-12-58 1.20/1.22													
*****100% VISUAL INSPECT FOR THE FOLLOWING*****														
<input checked="" type="checkbox"/> Hose fittings crimped;	<input checked="" type="checkbox"/> Air passes through assembly;													
<input checked="" type="checkbox"/> Presence of threads		<u>PM</u> <u>5-3-24</u>												
20 <input checked="" type="checkbox"/> Cap and package hose	<u>PM</u>	<u>5-3-24</u>												
	<u>PM</u>	<u>5-3-24</u>												



106CG-12-12

- 3 FITTING TYPE
- 01 NPT MALE
- 02 NPT FEMALE
- 03 JIC MALE
- 04 SAE 45 MALE
- 05 SAE O-RING STRAIGHT THREAD
- 06 JIC FEMALE SWIVEL
- 07 FEMALE PIPE SWIVEL


- 7 FITTING SIZE
- 4 1/4"
- 6 3/8"
- 8 1/2"
- 12 3/4"

- 1 58 SERIES HOSE SIZE
- 4 1/4"
- 6 3/8"
- 8 1/2"
- 10 5/8"
- 12 3/4"

- 4 FITTING TYPE
- 01 NPT MALE
- 02 NPT FEMALE
- 03 JIC MALE
- 04 SAE 45 MALE
- 05 SAE O-RING STRAIGHT THREAD
- 06 JIC FEMALE SWIVEL
- 07 FEMALE PIPE SWIVEL

- 8 FITTING SIZE
- 4 1/4"
- 6 3/8"
- 8 1/2"
- 12 3/4"

Cyt 105"



STANDARD 3" SHEREX 5/8" 5/8"

- 5 FITTING TYPE
- 01 NPT MALE
- 02 NPT FEMALE
- 03 JIC MALE
- 04 SAE 45 MALE
- 05 SAE O-RING STRAIGHT THREAD
- 06 JIC FEMALE SWIVEL
- 07 FEMALE PIPE SWIVEL

- 2 55 SERIES HOSE SIZE
- 2 1/8"
- 4 1/4"
- 6 3/8"

- 6 FITTING TYPE
- 01 NPT MALE
- 02 NPT FEMALE
- 03 JIC MALE
- 04 SAE 45 MALE
- 05 SAE O-RING STRAIGHT THREAD
- 06 JIC FEMALE SWIVEL
- 07 FEMALE PIPE SWIVEL

- 10 FITTING SIZE
- 2 1/8"
- 4 1/4"
- 6 3/8"

WORK ORDER #

5CNG1/5CNG1-0606/0506-1212/66-9 1 2 3 4 5 6 7 8 9 10 11

Tulsa Gas Technologies, Inc.  
 4809 S. 101st. E. Ave.  
 Tulsa, OK 74146  
 918-665-2641

Work Order # GHEM100423TS  
 Customer Name GHEM Construction  
 Customer PO NA  
 Date Required 5-3-24

ASSEMBLY/CERTIFICATION SHEET

	SIGN	DATE						
1 <input checked="" type="checkbox"/> Review shop work order versus customer print and history	PM	5-3-24						
2 <input checked="" type="checkbox"/> Component part numbers: <u>106CG-12-12, 106CG-12-12</u> Pack dates and/or QC codes _____	PM	5-3-24						
3 <input checked="" type="checkbox"/> ID band number <u>5CNG12/5CNG16-0606/0509-1212/66-36"</u>	PM	5-3-24						
4 <input checked="" type="checkbox"/> Hose Cut Length <u>36"</u>	PM	5-3-24						
5 _____ Pre-expansion of hose (if required) Size _____ Remarks: _____								
6 <input checked="" type="checkbox"/> Audit and mark appropriate insertion depth	PM	5-3-24						
7 _____ Add special accessories _____ Remarks: _____								
8 <input checked="" type="checkbox"/> Apply danger tag and ID band	PM	5-3-24						
9 <input checked="" type="checkbox"/> Install bend restrictors Remarks: _____	PM	5-3-24						
10 <input checked="" type="checkbox"/> Assemble fittings; check insertion depth Remarks: _____	PM	5-3-24						
11 _____ Set offset angle and/or orientation Remarks: _____								
12 <input checked="" type="checkbox"/> Perform crimp or swage on product/crimp set die-using Parker Catalog 4660, page K58  <table border="0" style="width: 100%; margin-left: 20px;"> <tr> <td>_____ 1/2) 80C-PO8H</td> <td>_____ 3/8) 80C-PO6H</td> </tr> <tr> <td>_____ 1/4) 80C-PO4H</td> <td>_____ 1/8) 80C-PO2</td> </tr> <tr> <td>_____ 3/8) 80C-PO6</td> <td><input checked="" type="checkbox"/> 3/4) 80C-P12H</td> </tr> </table>	_____ 1/2) 80C-PO8H	_____ 3/8) 80C-PO6H	_____ 1/4) 80C-PO4H	_____ 1/8) 80C-PO2	_____ 3/8) 80C-PO6	<input checked="" type="checkbox"/> 3/4) 80C-P12H	PM	5-3-24
_____ 1/2) 80C-PO8H	_____ 3/8) 80C-PO6H							
_____ 1/4) 80C-PO4H	_____ 1/8) 80C-PO2							
_____ 3/8) 80C-PO6	<input checked="" type="checkbox"/> 3/4) 80C-P12H							
13 _____ Add special accessories after crimping/swaging _____								
14 _____ Perform and record burst test results, if applicable Remarks: _____								
15 _____ Air test, if applicable Test pressure Psi _____ Seconds _____; Pass/Fail (Circle One) Remarks: _____								
16 <input checked="" type="checkbox"/> Hydrostatic proof test Test pressure Psi <u>10.000</u> Seconds <u>30</u> <input checked="" type="checkbox"/> Pass/Fail (Circle One) Remarks: _____	PM	5-3-24						
17 <input checked="" type="checkbox"/> Flush method water, and then air	PM	5-3-24						
18 <input checked="" type="checkbox"/> Perform and record conductivity test; Meter _____ Megger Mit200 Hose resistance <u>0.00</u> (-) Electrode resistance <u>0.03</u> (=) Final hose resistance <u>0.03</u>	PM	5-3-24						
19 <input checked="" type="checkbox"/> Final audit: Check boxes for items inspected, as applicable: <input checked="" type="checkbox"/> Correct hose; <input checked="" type="checkbox"/> Correct fittings; <input checked="" type="checkbox"/> Correct customer PN Check swage or crimp diameters: _____ 5CNG-4-58 .668/.688 _____ 5CNG-4-58 .785/.805 _____ 5CNG-8-58 .900/.920 _____ 5CNG-6-55 .675/.695 <input checked="" type="checkbox"/> 5CNG-12-58 1.20/1.22 *****100% VISUAL INSPECT FOR THE FOLLOWING***** <input checked="" type="checkbox"/> Hose fittings crimped; <input checked="" type="checkbox"/> Air passes through assembly; <input checked="" type="checkbox"/> Presence of threads	PM	5-3-24						
20 <input checked="" type="checkbox"/> Cap and package hose	PM	5-3-24						
_____	PM	5-3-24						

Tulsa Gas Technologies, Inc.  
 4809 S. 101st. E. Ave.  
 Tulsa, OK 74146  
 918-665-2641

Work Order # GHEM100423TS  
 Customer Name GHEM Construction  
 Customer PO NA  
 Date Required 5-3-24

ASSEMBLY/CERTIFICATION SHEET

	SIGN	DATE						
1 <input checked="" type="checkbox"/> Review shop work order versus customer print and history	<u>PM</u>	<u>5-3-24</u>						
2 <input checked="" type="checkbox"/> Component part numbers: <u>106CG-12-12, 106CG-12-12</u> Pack dates and/or QC codes _____	<u>PM</u>	<u>5-3-24</u>						
3 <input checked="" type="checkbox"/> ID band number <u>5CNG12/5CNG16-0606/0506-1212/66-96"</u>	<u>PM</u>	<u>5-3-24</u>						
4 <input checked="" type="checkbox"/> Hose Cut Length <u>36"</u>	<u>PM</u>	<u>5-3-24</u>						
5 _____ Pre-expansion of hose (if required) Size _____ Remarks: _____								
6 <input checked="" type="checkbox"/> Audit and mark appropriate insertion depth	<u>PM</u>	<u>5-3-24</u>						
7 _____ Add special accessories _____ Remarks: _____								
8 <input checked="" type="checkbox"/> Apply danger tag and ID band	<u>PM</u>	<u>5-3-24</u>						
9 <input checked="" type="checkbox"/> Install bend restrictors Remarks: _____	<u>PM</u>	<u>5-3-24</u>						
10 <input checked="" type="checkbox"/> Assemble fittings; check insertion depth Remarks: _____	<u>PM</u>	<u>5-3-24</u>						
11 _____ Set offset angle and/or orientation Remarks: _____								
12 <input checked="" type="checkbox"/> Perform crimp or swage on product/crimp set die-using Parker Catalog 4660, page K58  <table border="0" style="width: 100%;"> <tr> <td>_____ 1/2) 80C-PO8H</td> <td>_____ 3/8) 80C-PO6H</td> </tr> <tr> <td>_____ 1/4) 80C-PO4H</td> <td>_____ 1/8) 80C-PO2</td> </tr> <tr> <td><input checked="" type="checkbox"/> 3/8) 80C-PO6</td> <td><input checked="" type="checkbox"/> 3/4) 80C-P12H</td> </tr> </table>	_____ 1/2) 80C-PO8H	_____ 3/8) 80C-PO6H	_____ 1/4) 80C-PO4H	_____ 1/8) 80C-PO2	<input checked="" type="checkbox"/> 3/8) 80C-PO6	<input checked="" type="checkbox"/> 3/4) 80C-P12H	<u>PM</u>	<u>5-3-24</u>
_____ 1/2) 80C-PO8H	_____ 3/8) 80C-PO6H							
_____ 1/4) 80C-PO4H	_____ 1/8) 80C-PO2							
<input checked="" type="checkbox"/> 3/8) 80C-PO6	<input checked="" type="checkbox"/> 3/4) 80C-P12H							
13 _____ Add special accessories after crimping/swaging								
14 _____ Perform and record burst test results, if applicable Remarks: _____								
15 _____ Air test, if applicable Test pressure Psi _____ Seconds _____; Pass/Fail (Circle One) Remarks: _____								
16 <input checked="" type="checkbox"/> Hydrostatic proof test Test pressure Psi <u>10.000</u> Seconds <u>30</u> <u>(Circled)</u> ; Pass/Fail (Circle One) Remarks: _____	<u>PM</u>	<u>5-3-24</u>						
17 <input checked="" type="checkbox"/> Flush method water, and then air	<u>PM</u>	<u>5-3-24</u>						
18 <input checked="" type="checkbox"/> Perform and record conductivity test; Meter _____ Megger Mit200 Hose resistance <u>0.00</u> (-) Electrode resistance _____ 0.03 (=) Final hose resistance _____ 0.03	<u>PM</u>	<u>5-3-24</u>						
19 <input checked="" type="checkbox"/> Final audit: Check boxes for items inspected, as applicable: <input checked="" type="checkbox"/> Correct hose; <input checked="" type="checkbox"/> Correct fittings; <input checked="" type="checkbox"/> Correct customer PN Check swage or crimp diameters: _____ 5CNG-4-58 .668/.688 _____ 5CNG-4-58 .785/.805 _____ 5CNG-8-58 .900/.920 _____ 5CNG-6-55 .675/.695 <input checked="" type="checkbox"/> 5CNG-12-58 1.20/1.22 *****100% VISUAL INSPECT FOR THE FOLLOWING***** <input checked="" type="checkbox"/> Hose fittings crimped; <input checked="" type="checkbox"/> Air passes through assembly; <input checked="" type="checkbox"/> Presence of threads	<u>PM</u>	<u>5-3-24</u>						
20 <input checked="" type="checkbox"/> Cap and package hose	<u>PM</u>	<u>5-3-24</u>						
	<u>PM</u>	<u>5-3-24</u>						

106 CG-12-12


- 3 FITTING TYPE
- 01 NPT MALE
- 02 NPT FEMALE
- 03 JIC MALE
- 04 SAE 45 MALE
- 05 SAE O-RING STRAIGHT THREAD
- 06 JIC FEMALE SWIVEL
- 07 FEMALE PIPE SWIVEL

- 1 58 SERIES HOSE SIZE
- 4 1/4"
- 6 3/8"
- 8 1/2"
- 10 5/8"
- 12 3/4"

- 4 FITTING TYPE
- 01 NPT MALE
- 02 NPT FEMALE
- 03 JIC MALE
- 04 SAE 45 MALE
- 05 SAE O-RING STRAIGHT THREAD
- 06 JIC FEMALE SWIVEL
- 07 FEMALE PIPE SWIVEL

- 8 FITTING SIZE
- 4 1/4"
- 6 3/8"
- 8 1/2"
- 12 3/4"

Cut 36"



- 5 FITTING TYPE
- 01 NPT MALE
- 02 NPT FEMALE
- 03 JIC MALE
- 04 SAE 45 MALE
- 05 SAE O-RING STRAIGHT THREAD
- 06 JIC FEMALE SWIVEL
- 07 FEMALE PIPE SWIVEL

- 2 55 SERIES HOSE SIZE
- 2 1/8"
- 4 1/4"
- 6 3/8"

- 6 FITTING TYPE
- 01 NPT MALE
- 02 NPT FEMALE
- 03 JIC MALE
- 04 SAE 45 MALE
- 05 SAE O-RING STRAIGHT THREAD
- 06 JIC FEMALE SWIVEL
- 07 FEMALE PIPE SWIVEL

- 10 FITTING SIZE
- 2 1/8"
- 4 1/4"
- 6 3/8"

WORK ORDER #

1 5CNG 2/5CNG 6 - 06 106 / 05 06 - 12 12 / 66 - 36"

FILL HOSE

TULSA GAS TECHNOLOGIES, INC.  
 10117 EAST 48TH STREET  
 TULSA, OK 74116  
 918-605-2641 FAX: 918-605-2857  
 DATE: 03/27/87  
 DESIGNED BY: C. SEWELL  
 DRAWN BY: C.S.S.  
 CHECKED BY:  
 SCALE: NONE  
 DWG. NO. FILLHOSE.wor101dr.dwg2 SHEET NO. OF 1 REV. 1